



NCT-2

Non-Contacting Tachometer

| EQUIPMENT | DESCRIPTIVE | ITEM NUMBER |
|-----------|-------------|-------------|
|-----------|-------------|-------------|

Popular Packages (115 VAC)

| | | |
|---|----------------|----------|
| NCT-2, Nema 4 | NCT-2-5-1-1-__ | 90321000 |
| NCT-2, Nema 4, LCD Meter | NCT-2-5-1-2-__ | 90321100 |
| NCT-2, Nema 4, Dual Alarm Card | NCT-2-5-1-3-__ | 90321010 |
| NCT-2, Nema 4, LCD Meter & Dual Alarm Card | NCT-2-5-1-4-__ | 90321110 |
| NCT-2, Open Style | NCT-2-1-1-1-0 | 90311000 |
| NCT-2, Open Style, Dual Alarm Card, Backpan Mounted | NCT-2-1-1-3-__ | 90311010 |
| NCT-2, Nema 4X Stainless | NCT-2-9-1-1-__ | 90331000 |
| NCT-2, Nema 4X Stainless, LCD Meter | NCT-2-9-1-2-__ | 90331100 |
| NCT-2, Nema 4X Stainless, Dual Alarm Card | NCT-2-9-1-3-__ | 90331010 |
| NCT-2, Nema 4X Stainless, LCD Meter & Dual Alarm Card | NCT-2-9-1-3-__ | 90331110 |

Add the following suffix for Motion Sensing Probe and Remote Mounted Amplifier (if needed) selection in ____:

| | | |
|---|---|--------------------------|
| MSP-1 (with RMA in Nema 4) (Manufactured by Westec) | | 7MH7146-0AA + 7MH7145-0A |
| MSP-12 Low Temperature Probe | 1 | 7MH7146-0EA |
| MSP-3 High Temperature Probe (with RMA in Nema 4) | 2 | 7MH7146-0BA + 7MH7145-0A |
| XPP-5 Explosion Proof Probe (with 5 feet of cable) | 3 | 7MH7146-0GA |
| XPP-5 Explosion Proof Probe (with 30 feet of cable) | 4 | 7MH7146-0HA |
| MSP-9 304 SS Probe (with RMA in Nema 4 SS) | 6 | 7MH7146-0DA + 7MH7145-0D |

Optional Equipment and Parts

| | |
|--|-------------|
| 230 Volt Operation | Optional |
| LCD Meter | 51007611 |
| Dual Alarm Card | 51007421 |
| RMA Circuit Board | 7MH7723-1DT |
| Fuses, Box of 5, 2/10 Amp, Slo-Blo (For 115 VAC) | 22550055 |
| Fuses, Box of 5, 1/10 Amp, Slo-Blo (For 230 VAC) | 22550056 |
| Transformer, 30A190, (For 115 VAC) | 26350190 |
| Transformer, 30A241, (For 230 VAC) | 26350241 |
| Extra NCT-2 Manual | IM-3 |